



TO EXTERNAL CLOCK CIRCUITS
AND POWER AS REQUIRED.

APPROVED MAGNETIC STARTER/
THERMAL OVERLOAD ASSEMBLY

"IN SIGHT" DISCONNECT
(IF REQUIRED BY CODE)

GREEN GROUND LUG

JUNCTION BOX

USE COPPER CONDUCTORS &
APPROVED CONNECTORS ONLY

THREE PHASE UNITS